

Drive Shaft - Dorman University Questions:

1. Drive Shaft replacements have traditionally been considered?
 - a. An impossible repair
 - b. Dealer Only repairs
 - c. Unavailable
 - d. A high cost specialized repair

2. How many Drive Shaft Assembly SKUs, and vehicles applications does Dorman currently offer?
 - a. Over 125 SKUs, covering 10 MM VIO
 - b. Over 250 SKUs, covering 36 MM VIO
 - c. Over 300 SKUs, covering 75 MM VIO
 - d. Over 325 SKUs, covering 152 MM VIO

3. True or false, a failed Universal Joint will create excessive play within a Drive Shaft?
 - a. True
 - b. False

4. A Failed Center Support Bearing will cause excessive vertical and horizontal movement resulting in?
 - a. Driveline Vibration
 - b. No issues
 - c. Uneven tire wear
 - d. Vehicle doors to randomly open

5. True or false, a Drive Shaft Bump stop/Clunk can be misdiagnosed as a failed Transmission Mount or Engine Mount?
 - a. True
 - b. False

6. True or false, a Staked U-Joint is a serviceable component?
 - a. True
 - b. False

7. Dorman's U-Joints can be identified by which of the following characteristics?
 - a. Shape of the center support bearing
 - b. Staked material on the Drive Shaft Yokes
 - c. Retaining clips used to hold the Universal Joint in place
 - d. All of the above

8. True or false, Dorman's Drive Shaft Assemblies are designed with serviceable components?
 - a. True
 - b. False

9. Dorman's Drive Shaft program is available as a?
 - a. Drop-Ship Program
 - b. 100 % New Program
 - c. Stocking Program
 - d. All of the above